

# Oil Field Environmental Incident Summary

**Incident:** 20160212111047      **Date/Time of Notice:** 02/12/2016 11:10

**Responsible Party:** ZAVANNA, LLC

**Well Operator:** ZAVANNA, LLC

**Well Name:** BRUCE 5-8 1H

**Field Name:** CRAZY MAN CREEK

**Well File #:** 19982

**Date Incident:** 2/11/2016      **Time Incident:** 14:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 153

**Rng:** 99

**Sec:** 5

**Qtr:**

**Location Description:** Spill is on the snow/land area south of the pad

**Submitted By:** Kimberly Gutierrez

**Received By:**

**Contact Person:** Kimberly Gutierrez  
1200 17TH STREET STE 1100  
DENVER, CO 80202

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	0.3	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/24/2016

**Clean Up Concluded:** 2/11/2016

**Risk Evaluation:**

none

**Areal Extent:**

land south of location

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

The land owner and NDIC Inspector did not require snow to be removed nor any further clean up.

**Wastes Disposal Location:** n/a

**Agencies Involved:**

**Updates**

---

**Date:** 2/12/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the landowner and NDIC did not require any cleanup of the release. However, the release impacted an area off the well pad. Further followup needed.

---

**Date:** 2/24/2016    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

2/24/2016 at 10:45, on location. Checked pasture land south of wellpad. Electrical fence insulators show faint staining. New fallen snow has no visible impact; however, snow that was present during the incident may have already melted. Since landowner has indicated that no further cleanup needs to be done, no further followup is required.